

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2017

Submitted Date:

09/08/2017

Document Number:

685303714**FIELD INSPECTION FORM**
 Loc ID 381594 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100178Name of Operator: D J SIMMONS INCAddress: P.O. BOX 1469City: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Leonard, Mike		mike.leonard@state.co.us	
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
Telecky, Barbara		btelecky@blm.gov	Durango

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208991	WELL	PR	03/01/2017	GW	033-06096	RANGER-FEDERAL 16-19	PR

General Comment:[See link at end of report for path to downloadable pictures.](#)[Inspection completed to inventory flowlines/risers and check compliance to May 2017 Flowline NTO.](#)[Inspection report contains corrective action and comment.](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt and gravel access road. Road has become over grown with vegetation.		
Corrective Action	L	Date:	

Overall Good: ☐

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Thistle noted in previous inspection and was not removed and has to seed.		
Corrective Action:	Remove weeds to comply with Rule 603.f.		Date: 09/18/2017
Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment. Not in use - Steel 1" supply gas line stubbed up at front of separator and stubbed up out at wellhead. Not in use - Steel 2" line stub up at front of separator to stub up inside tank berms. Corrective action not completed. Corrective action date remains the same to document days of noncompliance.		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: 05/30/2017

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	Not in use - Steel 1" supply gas line stubbed up at front of separator and stubbed up out at wellhead.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Not in use - Steel 2" line stub up at front of separator to stub up inside tank berms.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:	Above ground 210 BBL steel tank with earthen berms.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds growing inside and on berms.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 10/08/2017

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 208991 Type: WELL API Number: 033-06096 Status: PR Insp. Status: PR**Producing Well**Comment: PR - Review of electronic well file indicates last reported production was May 2017 with oil/gas reported as 58/5383.

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

Well was running at time of inspection.

stjohnw

08/31/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303723	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4247088