

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/07/2017

Submitted Date:

09/08/2017

Document Number:

685303738

FIELD INSPECTION FORM

Loc ID 322094 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100178
Name of Operator: D J SIMMONS INC
Address: P.O. BOX 1469
City: FARMINGTON State: NM Zip: 87401

Findings:

- 29 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Telecky, Barbara		btelecky@blm.gov	Durango

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208950	WELL	PR	11/17/2006	GW	033-06055	SANTA FE CANYON FED 42-7	SI

General Comment:

[See link at end of report for path to downloadable pictures.](#)
[Inspection completed to inventory flowlines/risers and check compliance with May 2017 Flowline NTO.](#)
[Inspection report contains corrective action and comment.](#)

Location			
Lease Road:			
Type	Access		
comment:	Dirt access road off county road.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels directly on tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal sign mounted on gas meter run shed.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign. 505-326-3753 number goes to voicemail for the offices of D J Simmons.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	OTHER		
Comment:	Impacted soil and gravel along joints and valves in tank battery. Less than 5 gallon bucket clean up.		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	Production pad over grown with weed, grass, sage brush, and thistle.		
Corrective Action:	Remove weeds to comply with Rule 603.f.	Date:	09/19/2017
Type	UNUSED EQUIPMENT		
Comment:	Identified (22) unused risers/flowlines. Flowline risers not LO/TO or marked are considered unused equipment. Risers painted orange by inspector.		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	10/09/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Steel and wooden post with wire fencing. Fencing is down in areas.		
Corrective Action:		Date:	
Equipment:			
Type: Ancillary equipment	# 1		corrective date

Comment:		Wellhead. Disconnected from flowline. Open ended lines on wellhead and flowline.		Date:	
Corrective Action:				Date:	
Type: Deadman # & Marked	# 2				
Comment:		Located 2 deadmen. Deadmen not marked.		Date:	
Corrective Action:		Locate and mark all deadmen to comply with Rule 1003.a.		Date:	10/09/2017
Type: Flow Line	# 15				
Comment:		<p>Wellhead area.</p> <p>Not in use - 4" steel line from wellhead to separator inlet. All points co-located.</p> <p>Not in use - 1" steel riser at wellhead. Open ended.</p> <p>Separator area.</p> <p>In use - (3) 3" steel risers from separator outlets. (B) points unknown.</p> <p>Not in use - (2) 2" steel risers to S of separator. (B) points unknown.</p> <p>Not in use - (3) 1" steel risers to S of separator. (B) points unknown.</p> <p>In use - 1" steel line from separator oil dump to production tank. All points co-located.</p> <p>Tank battery.</p> <p>Not in use - (2) 3" steel risers inside tank battery berms. Left from removed tanks.</p> <p>Not in use - (2) 4" steel risers inside tank battery berms. Left from removed tanks.</p>		Date:	
Corrective Action:				Date:	
Type: Flow Line	# 2				
Comment:		<p>In use - 3" steel riser beside meter house. Line comes out of the ground and goes back into the ground. (A) and (C) points unknown.</p> <p>In use - 3" steel riser to E of meter house. Line comes out of ground horse shoes and goes back into ground. (A) and (C) points unknown.</p>		Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Flow Line	# 11				
Comment:		<p>Not in use - (2) 3" steel risers on N side of location W of meter run house. (B) point unknown.</p> <p>Not in use - 1" steel line on N side of location. (B) point unknown.</p> <p>Not in use - 3" steel line open to atmosphere coming into meter house. (B) point unknown.</p> <p>Not in use - 3" steel riser at meter house. (B) point unknown.</p> <p>Not in use - (6) 3" steel risers to the E of meter house. (B) points unknown.</p>		Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:		Telemetry equipment.		Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,

Comment:	Above ground 210 BBL tank with earthen berms. 10' 1" OF FLUID IN TANK.	
Corrective Action:		Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Concrete	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms are weathered. Patches of weeds and grass noted growing inside bermed area.			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST		,

Comment:	Above ground 400 BBL tank with earthen berms. FLUID LEVELS IN TANKS. Tank 1 - 0' 6" Tank 2 - 2' 1"	
Corrective Action:		Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms are weathered. Patches of weeds and grass noted growing inside berms.			
Corrective Action:			Date:	

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 208950 Type: WELL API Number: 033-06055 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI - Review of electronic well file indicates last reported production as October 2016 with production numbers reported as 250/5. Well has been reported as SI since september 2016 with last production report submitted May 2017.

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Location has agricultural fields to the N and canyon to the S. There appears to be a soil pile on the S side of the tank battery.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Fail _____

Comment NW corner of location has graveled area and partial berms. Equipment has been removed.

Corrective Action Remove gravel, berms, and soil pile and reclaim unused area to comply with Rule 1002.e.

Date **12/08/2017**

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date _____

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment

Corrective Action

Date _____

Guy line anchors marked? Fail

Comment Deadmen not marked.

Corrective Action Locate and mark all deadmen to comply with Rule 1003.a.

Date **10/09/2017**

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around produced water tank.
Culverts	Pass					
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
May 2017 Flowline NTO not completed. Inspector painted unused risers orange. There are fluids in the production tanks.	stjohnw	09/07/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303747	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4247500