

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/07/2017

Submitted Date:

09/11/2017

Document Number:

690100103

FIELD INSPECTION FORM

Loc ID 320460 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10454
Name of Operator: PETROSHARE CORPORATION
Address: 9635 MAROON CIRCLE #400
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	
Hazard, Ellice		ellice.hazard@state.co.us	
Witsell, Fred	303-500-1168	fwitsell@petrosharecorp.com	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203819	WELL	SI	04/01/2017	GW	001-09379	EHLER 44-4	TA

General Comment:

Details of Corrective Actions Required identified during this field inspection are available in the equipment/ flowline and housekeeping sections of this report. Photo's uploaded can be accessed via link(s) at the end of this report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Misc trash (concrete debris/ wood planks, etc) near wellhead and around location.		
Corrective Action:	Comply with Rule 603.f ; Remove trash from location.	Date:	09/21/2017
Type	WEEDS		
Comment:	Excessive weeds near wellhead and on location.		
Corrective Action:	Comply with Rule 603.f ; Remove existing weeds and impliment program to control future weed growth.	Date:	09/21/2017

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203819 Type: WELL API Number: 001-09379 Status: SI Insp. Status: TA**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Well has been Temporarily Abandoned; flowline(s) disconnected/ abandoned. No current MIT on record or delinquent as required by Rule 326.Corrective Action: No current MIT on record or delinquent as required by Rule 326; Contact dnr_cogccengineering@state.co.us with resolution plan.Date: 09/21/2017**COGCC Comments**

Comment	User	Date
The Actions Required identified on the Environmental Inspection Doc #679500211 performed on 04/06/2017 must be completed as outlined.	maclarej	09/08/2017
Note: There is a natural gas gathering pipe riser located on the Northeast corner of location. The following COGCC final reclamation rule(s) may be applicable in future: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.	maclarej	09/08/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100104	Wellhead, Temporarily Abandoned	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248052
690100105	Weeds and trash on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248053
690100106	Gas gathering riser on NE corner location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248054