

Inspection Photos
Location Name: Texaco Fee 6214
Location ID: 323831



Photo 1. Access road is heavily eroded.



Photo 2. Culvert is damaged and non-functional.