

Construction and Stormwater Inspection

September 8, 2017

Operator: CRESCENT POINT ENERGY U.S. CORP - #10520

Location ID: 447898

Weld County, CO

SESW Section 31 T9N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Anderson Facility
Location ID: 447898



Photo 1. Photo taken from the western location, facing East. Topsoil salvage operations IN-PROCESS. Temporary BMP (i.e., ditch) installed around in the entire perimeter of the location.



Photo 2. Photo taken from the northwest location, facing East. Topsoil salvage operations IN-PROCESS. Temporary BMP (i.e., ditch) installed around in the entire perimeter of the location.

Inspection Photos
Location Name: Anderson Facility
Location ID: 447898



Photo 3. Photo taken from the northwest location, facing South. Topsoil salvage operations IN-PROCESS. Temporary BMP (i.e., ditch) installed around in the entire perimeter of the location.



Photo 4. Photo taken from the Southwest location, facing East. Topsoil salvage operations IN-PROCESS. Temporary BMP (i.e., ditch) installed around in the entire perimeter of the location.