

Inspection Photos
Location Name: Bird-State 32-1
API: 05-005-06589
Inspection Date: September 7, 2017



Photo #1 – Well sign on south side of entrance from access road.



Photo #2 – Workover rig on-site on date of inspection.

Inspection Photos
Location Name: Bird-State 32-1
API: 05-005-06589
Inspection Date: September 7, 2017



Photo #3 – Battery sign.



Photo #4 – Tank battery.

Inspection Photos
Location Name: Bird-State 32-1
API: 05-005-06589
Inspection Date: September 7, 2017



Photo #5 – VHT shed with day tanks inside of berm.



Photo #6 – NFPA placard for VHT shed is damaged.

Inspection Photos
Location Name: Bird-State 32-1
API: 05-005-06589
Inspection Date: September 7, 2017



Photo #7 – Inside of the VHT shed has been cleaned in response to corrective actions listed on previous FIR.



Photo #8 – Laydown yard with pipe racks located on west side of location. Note that cuttings have been applied to yard (grey material overlying soil).

Inspection Photos
Location Name: Bird-State 32-1
API: 05-005-06589
Inspection Date: September 7, 2017



Photo #9 – Northern end of silt fence that runs along west side of location.



Photo #10 – Southern end of silt fence that runs along west side of location. Silt fence in need of repair/maintenance. Note sediment transport west of silt fence.

Inspection Photos
Location Name: Bird-State 32-1
API: 05-005-06589
Inspection Date: September 7, 2017



Photo #11 – Localized, oil-stained soil and gravel beneath 1” valve on SW side of AST located at workover rig.



Photo #12 – Area being remediated under Remediation Project #9615 had been scraped prior to inspection date.

Inspection Photos
Location Name: Bird-State 32-1
API: 05-005-06589
Inspection Date: September 7, 2017



Photo #13 – Junk pipe and gravel north of entry to location.



Photo #14 – Junk pallet, wood debris, and gravel north of entry to location.