

Inspection Photos



Photo 1. The powerline utility remains at CO Rd 56 which appears to have serviced the location and now appears to be abandoned.

Inspection Photos



Photo 2. An abandoned pipe riser remains at the location.

Lat/Long:37.17655,-102.06051

Inspection Photos



Photo 4. Facing southwest at the location. This area does not have any vegetation growth and could have possible soil issues.

Inspection Photos



Photo 4. West side of the location facing east. This area does not have any vegetation growth and could have possible soil issues.

Inspection Photos



Photo 4. North side of the location facing east.