

# Inspection Photos

9/5/2017

Operator: NIGHTHAWK PRODUCTION LLC -  
10399

Location ID: 437624

Inspection Doc. Number: 675103920  
Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NIGHTHAWK PRODUCTION LLC - 10399  
Location ID: 437624



**Photo 1:** Photo taken from the northwest corner of the location, facing east. Photo shows vegetation over the reclamation area is predominantly undesirable weedy plant species and not reflective of the adjacent reference area. Well was PA'd 2014, at least three growing seasons have passed.



**Photo 2:** Photo taken from the northwest corner of the location, facing southeast. Photo shows vegetation over the reclamation area is predominantly undesirable weedy plant species and not reflective of the adjacent reference area. Well was PA'd 2014, at least three growing seasons have passed.

Inspection Photos  
Operator: NIGHTHAWK PRODUCTION LLC - 10399  
Location ID: 437624



**Photo 3:** Photo taken from the northwest corner of the location, facing south. Photo shows vegetation over the reclamation area is predominantly undesirable weedy plant species and not reflective of the adjacent reference area. Well was PA'd 2014, at least three growing seasons have passed



**Photo 4:** Photo taken from the central portion of the location, facing south. Photo shows vegetation over the reclamation area is predominantly undesirable weedy plant species and not reflective of the adjacent reference area. Well was PA'd 2014, at least three growing seasons have passed

Inspection Photos  
Operator: NIGHTHAWK PRODUCTION LLC - 10399  
Location ID: 437624



**Photo 5:** Photo taken from the adjacent reference area, facing east. Photo shows the start point for the reference area transect.



**Photo 6:** Photo shows vegetation at the 50th point of the reference area transect, facing north.

Inspection Photos  
Operator: NIGHTHAWK PRODUCTION LLC - 10399  
Location ID: 437624



**Photo 7:** Photo shows vegetation at the 50th point of the reference area transect, facing south.



**Photo 8:** Photo shows vegetation at the 50th point of the reference area transect.

Inspection Photos  
Operator: NIGHTHAWK PRODUCTION LLC - 10399  
Location ID: 437624



**Photo 9:** Photo taken from the adjacent reference area, facing west. Photo shows the end point for the reference area transect.



**Photo 10:** Photo taken from the location, facing south. Photo shows the start point for the disturbance area transect.

Inspection Photos  
Operator: NIGHTHAWK PRODUCTION LLC - 10399  
Location ID: 437624



**Photo 11:** Photo shows vegetation at the 50th point of the disturbance area transect, facing west.



**Photo 12:** Photo shows vegetation at the 50th point of the disturbance area transect, facing east.



**Photo 13:** Photo shows vegetation at the 50th point of the disturbance area transect.



**Photo 14:** Photo taken from the disturbance area, facing north. Photo shows the end point for the disturbance area transect.