

Inspection Photos



Photo 1. 2016 aerial imagery shows location of well site. There is no crop growth shown in an area approximately 250' x 100'.

Inspection Photos



Photo 2. West side of the location facing east. There is a lack of crop growth at the location.

Inspection Photos



Photo 3. South side of the location facing northeast. There appears to be soil issues affecting crop growth.

Inspection Photos



Photo 4. East side of the location facing west.

Inspection Photos



Photo 5. Facing west toward the surrounding crop growth off the location.