

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/30/2017

Submitted Date:

09/12/2017

Document Number:

680601995**FIELD INSPECTION FORM**

Loc ID 325157 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96705Name of Operator: WPX ENERGY PRODUCTION LLCAddress: P O BOX 3102 MS-25-2City: TULSA State: OK Zip: 74101**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email   | Comment                         |
|--------------|-------|---|---------------------------------|
| , General    |       | COGCCinspectionreportsSan<br>Juan@wpxenergy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 214152      | WELL | PR     | 12/21/1959  | GW         | 067-05469 | IGNACIO 33-7 7 | RI          |

**General Comment:**

[This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.](#)

| Inspected Facilities |               |       |             |             |                  |         |           |               |           |
|----------------------|---------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID:         | <u>214152</u> | Type: | <u>WELL</u> | API Number: | <u>067-05469</u> | Status: | <u>PR</u> | Insp. Status: | <u>RI</u> |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by pinion juniper woodland. Revegetation is progressing within most of the interim reclamation areas, and weedy in other areas.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment Metal cable is present in the eastern portion of the interim reclamation area (lower tier fill slope).Corrective Action Remove cable.Date **10/13/2017**Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

|   |   |
|---|---|
| 1003b. Area no longer in use? _____ In _____  | Production areas stabilized ? _____   |
| 1003c. Compacted areas have been cross ripped? _____  |   |
| 1003d. Drilling pit closed? _____   | Subsidence over on drill pit? _____   |
| Cuttings management: _____  |   |
| 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ In _____ |   |
| Production areas have been stabilized? _____  | Segregated soils have been replaced? _____  |
| <b>RESTORATION AND REVEGETATION</b>   |   |
| <u>Cropland</u>   |   |
| Top soil replaced _____   | Recontoured _____ Perennial forage re-established _____   |
| <u>Non-Cropland</u>   |   |
| Top soil replaced _____   | Recontoured _____ 80% Revegetation _____ In _____   |
| 1003e. INTERIM VEGETATION TRANSECT  |   |
| TRANSECT RESULTS OF DISTURBED AREA% _____   |   |
| TRANSECT RESULTS OF REFERENCE AREA% _____   |   |
| TOTAL % OF DESIRABLE VEGETATION COVER _____   |   |
| VEGETATIVE COVER _____  |   |
| 1003 f. Weeds Noxious weeds? _____ I _____  |   |
| Comment   | <div style="border: 1px solid black; padding: 2px;">Scattered musk thistles are present. Weeds appear to have been treated in 2017.</div> |
| Corrective Action   | <div style="border: 1px solid black; height: 20px;"></div>  |
| Date  | _____   |
| Overall Interim Reclamation   | In Process  |

---

**Final Reclamation/ Abandoned Location:**

|   |   |
|---|---|
| Date Final Reclamation Started: _____                               | Date Final Reclamation Completed: _____   |
| Final Land Use: _____   |   |
| Reminder: _____   |   |
| Comment: <div style="border: 1px solid black; height: 20px;"></div> |   |
| Well plugged _____  | Pit mouse/rat holes, cellars backfilled _____   |
| Debris removed _____  | No disturbance /Location never built _____  |
| Access Roads Regraded _____   | Contoured _____ Culverts removed _____  |
| Gravel removed _____  |   |
| Location and associated production facilities reclaimed _____       | Locations, facilities, roads, recontoured _____   |
| Compaction alleviation _____  | Dust and erosion control _____  |
| Non cropland: Revegetated 80% _____                                 | Cropland: perennial forage _____  |
| Weeds present _____   | Subsidence _____  |
| 1004.d. FINAL VEGETATION TRANSECT                                   |   |
| TRANSECT RESULTS OF DISTURBED AREA% _____                           |   |
| TRANSECT RESULTS OF REFERENCE AREA% _____                           |   |
| TOTAL % OF DESIRABLE VEGETATION COVER _____                         |   |
| VEGETATIVE COVER _____  |   |
| Comment:  | <div style="border: 1px solid black; height: 20px;"></div>  |
| Corrective Action:  | <div style="border: 1px solid black; height: 20px;"></div>  |
| Date  | _____   |
| Overall Final Reclamation _____                                     | Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Erosional channels are forming where concentrated stormwater flows off of the eastern portion of the working area. See attached photos.

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area. Date: 10/13/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 680601996    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4249407">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4249407</a> |