

Inspection Photos

Location Name: Wells Ranch USX AA 23-67HN Pad

API: 05-123-35338



Photo 1: Wellheads, looking SE



Photo 2: Stained soil at wellhead



Inspection Photos

Location Name: Wells Ranch USX AA 23-67HN Pad

API: 05-123-35338



Photo 3: Stained soil at pumping unit wellhead



Photo 4: Stained soil at generator

