

Inspection Photos
Location Name: Wells Ranch USX AE #19-14
API: 05-123-25739



Photo 1: Location, looking SE



Photo 2: Wellhead, looking SE



Inspection Photos
Location Name: Wells Ranch USX AE #19-14
API: 05-123-25739



Photo 3: Damaged placard



Photo 4: Unused fencing



Inspection Photos
Location Name: Wells Ranch USX AE #19-14
API: 05-123-25739



Photo 5: Unused fencing



Photo 6: Stained soil at engine

Inspection Photos
Location Name: Wells Ranch USX AE #19-14
API: 05-123-25739

