

Inspection Photos
Location Name: E. Johnson 2-21
API: 05-123-21260



Wellhead looking north



**Access road to wellhead from battery looking southeast.
Road is washing out on both sides**

Inspection Photos
Location Name: E. Johnson 2-21
API: 05-123-21260



Lease road to battery is washing out, looking north



Battery looking east from southwest edge of location

Inspection Photos
Location Name: E. Johnson 2-21
API: 05-123-21260



Location washing out south side of separator



Location washing out north side of location, discharging northwest of tank battery with sediment carrying off into field



Inspection Photos
Location Name: E. Johnson 2-21
API: 05-123-21260



Access road to wellhead looking south from battery. Actively growing weeds need to be controlled.

