

Inspection Photos  
Location Name: Fuqua 19-02-10-1H  
API: 05-057-06483



**Photo 1. Overview of location taken at entrance facing southeast.**

Inspection Photos  
Location Name: Fuqua 19-02-10-1H  
API: 05-057-06483



Photo 2. Equipment storage/evidence of recent fire.



Photo 3. Equipment storage/evidence of recent fire.

Inspection Photos  
Location Name: Fuqua 19-02-10-1H  
API: 05-057-06483



**Photo 4. Flare knocked over. 1 – 1” and 1 – 2” steel risers.**



**Photo 5. Equipment storage.**

Inspection Photos  
Location Name: Fuqua 19-02-10-1H  
API: 05-057-06483



Photo 6. Topsoil pile with recent soil removal and dried annual weeds.



Photo 7. Equipment storage/evidence of recent fire.