

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Photo 1. Overview of location taken at entrance facing south.



Photo 2. Equipment stored on location.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Photo 3. Equipment stored on location.



Photo 4. Unconsolidated berm.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Photo 5. Erosion rills coming onto location.



Photo 6. Erosion rills coming onto location.