

## Inspection Photos



**Photo 2.** West side of the location facing east. There is a lack of crop growth at the location.

## Inspection Photos



**Photo 3.** East side of the location facing west. There appears to be soil issues affecting crop growth.



## Inspection Photos



**Photo 5.** Facing south toward the surrounding crop growth off the location.