

Inspection Photos



Photo 2. West side of the location facing east. There is a lack of crop growth at the location.

Inspection Photos



Photo 3. East side of the location facing west. There appears to be soil issues affecting crop growth.

Inspection Photos



Photo 5. Facing north toward the surrounding crop growth off the location.