

Inspection Photos



Photo 1. Facing north toward the location. The desirable vegetation has not adequately established at the location.

Inspection Photos



Photo 2. Northern side of the location facing south. A 100ft tape measure is laid out at the location. There is predominately undesirable weeds in this area.

Inspection Photos



Photo 3. Center of the location facing west.

Inspection Photos



Photo 4. The soils at the location appear to be compacted. The shovel shown in the photo was unable to penetrate into the soil.

Inspection Photos



Photo 5. There is a t-post and wire that remains at the southeast side of the location.

Inspection Photos



Photo 6. Facing north toward the surrounding undisturbed pasture.