

**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 1: Stained soil at wellhead**



**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 2: Wellhead sign is for prior operator**



**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 3: Stained soil at crude oil loadouts removed or remediated. Leaking stopped.**

**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 4: Damaged placards on crude oil tanks**



**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 5: Production tank lacking placarding**

**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 6: Stained soil at SE corner of pumphouse**



**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 7: Stained soil at SW corner of pumphouse, unused equipment removed.**

**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 8: Stained soil in treater house**



**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 9: Gaps in netting on pit**

**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 10: Stormwater erosion on N side of pit.**



**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 11: Unused equipment at battery**

**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 12: Unmarked unused risers at location.**



**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 13: Stained soil at NW corner of pit**

**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 14: Battery sign reattached**



**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 15: Debris in treater house**

**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 16: Oily residue in pump house**



**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 17: Stained soil at produced water**

**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo from prior inspection for comparison**



**Photo 18: Stained soil at produced water tank**



**Inspection Photos**  
**Location Name: Hill #31-15-8**  
**API: 05-123-19368**



**Photo 19: Stormwater runoff on S side of pit**