

**Inspection Photos**  
**Location Name: Hill #31-9-11**  
**API: 05-123-19627**



**Photo from prior inspection for comparison**



**Photo 1: Stained soil at engine house**

**Inspection Photos**  
**Location Name: Hill #31-9-11**  
**API: 05-123-19627**



**Photo from prior inspection for comparison**



**Photo 2: Stained soil at pump jack**



**Inspection Photos**  
**Location Name: Hill #31-9-11**  
**API: 05-123-19627**



**Photo from prior inspection for comparison**



**Photo 3: Unused equipment by pump jack.**

**Inspection Photos**  
**Location Name: Hill #31-9-11**  
**API: 05-123-19627**



**Photo from prior inspection for comparison**



**Photo 4: Stained soil at engine**