

Inspection Photos
Location Name: Dinner E 14-5
API #: 05-123-25471



Wellhead looking east. Well is in active crops



Battery looking west

Inspection Photos
Location Name: Dinner E 14-5
API #: 05-123-25471



Leaking valve at gas meter run that is staining soil.



Tank battery looking west