

Inspection Photos
Location Name: Merrion Oil & Gas
API 05-103-10024
9/13/2017



Looking north at dump line spill point into former pit



Historic contamination east end of former pit

Inspection Photos
Location Name: Merrion Oil & Gas
API 05-103-10024
9/13/2017



Looking north at landfarm under construction



Looking southeast at excavation from AST