

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/30/2017

Submitted Date:

09/08/2017

Document Number:

685303710

FIELD INSPECTION FORM

Loc ID 322107 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100178
Name of Operator: D J SIMMONS INC
Address: P.O. BOX 1469
City: FARMINGTON State: NM Zip: 87401

Findings:

- 21 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208980	WELL	PR	05/04/2010	GW	033-06085	WILLIE WASCHKE 4-17	SI

General Comment:

[See link at end of report for path to downloadable pictures.](#)
[May 2017 Flowline NTO was incorporated into field inspection to inventory flowlines and compliance check.](#)
[Inspection report contains corrective actions and comments.](#)

Location						
Lease Road:						
Type	Access					
comment:	Dirt and gravel access road. Road is covered in weed and grass.					
Corrective Action	L				Date:	
Overall Good: <input type="checkbox"/>						
Signs/Marker:						
Type	TANK LABELS/PLACARDS					
Comment:	Label directly on tank. Labels are peeling.					
Corrective Action:					Date:	
Type	WELLHEAD					
Comment:	Framed metal sign at tank battery,					
Corrective Action:					Date:	
Emergency Contact Number:						
Comment:	Operator contact on wellhead sign. 505-326-3753 goes to voice mail for offices of D J Simmons.					
Corrective Action:					Date:	
Good Housekeeping:						
Type	UNUSED EQUIPMENT					
Comment:	One flowline riser identified. Flowline risers not LO/TO or marked are considered unused equipment					
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.				Date:	10/08/2017
Overall Good: <input type="checkbox"/>						
Spills:						
Type	Area	Volume				
In Containment: No						
Comment:						
<input type="checkbox"/> Multiple Spills and Releases?						
Fencing/:						
Type	LOCATION					
Comment:	Post and wire fencing.					
Corrective Action:					Date:	
Equipment:						
Type:	Horizontal Heated Separator	# 1				corrective date
Comment:						
Corrective Action:					Date:	
Type:	Gas Meter Run	# 1				
Comment:						
Corrective Action:					Date:	
Type:	Bird Protectors	# 1				

Comment:		Date:	
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Well has been disconnected from flowline.		
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	Not in use - 3" steel line from riser at wellhead to separator inlet. Wellhead end taped and painted. All points co-located. In use - 3" steel line from separator pressure relief valve to tank line. All points co-located. In use - 3" steel line from separator outlet to gas meter inlet. All points co-located. In use - 3" steel line from separator oil dump to tanks. All points co-located. In use - 3" steel line from separator water dump line to tanks. All points co-located.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Located 1 deadman. Not all anchors marked.		
Corrective Action:	Locate and mark all deadmen to comply with Rule 1003.a.	Date:	10/08/2017

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:	Above ground 400 BBL steel tank with earthen berms. THERE IS 7"1" OF FLUIDS IN THE TANK AT TIME OF INSPECTION.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms are weathering.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:	Above ground 400 BBL steel tank with earthen berms. THERE IS 1'4" OF FLUIDS IN THE TANK AT TIME OF INSPECTION.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms are weathered.					
Corrective Action:				Date:	

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 208980 Type: WELL API Number: 033-06085 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI - Well is disconnected from flowline. Production equipment on location and connected. Review of electronic wele file indicates last reported production was July 2016 with oil/gas production reported as 78/1. Well has been reported as SI since August 2016. Last submitted production report was May 2017.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Rural agriculture property with open grazing and planted field surrounding location.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Fail

Comment Not all anchors marked.

Corrective Action Locate and mark all deadmen to comply with Rule 1003.a.

Date 10/08/2017

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around production tanks.
Comment: <input type="text" value="Stormwater BMPs appear to be functioning at time of inspection."/>						
Corrective Action: <input type="text"/>					Date: _____	
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
Wellhead has been disconnected from flowline. There is fluid in both tanks. Water tank guages at 1'4" and oil tank guages at 7'1".	stjohnw	08/30/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401398681	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4247096
685303719	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4247084