

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/31/2017

Submitted Date:

09/08/2017

Document Number:

685303714

FIELD INSPECTION FORM

Loc ID 381594 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100178
 Name of Operator: D J SIMMONS INC
 Address: P.O. BOX 1469
 City: FARMINGTON State: NM Zip: 87401

Findings:

- 13 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Telecky, Barbara		btelecky@blm.gov	Durango
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208991	WELL	PR	03/01/2017	GW	033-06096	RANGER-FEDERAL 16-19	PR

General Comment:

[See link at end of report for path to downloadable pictures.](#)

[Inspection completed to inventory flowlines/risers and check compliance to May 2017 Flowline NTO.](#)

[Inspection report contains corrective action and comment.](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt and gravel access road. Road has become over grown with vegetation.		
Corrective Action	L		Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Thistle noted in previous inspection and was not removed and has to seed.		
Corrective Action:	Remove weeds to comply with Rule 603.f.		Date: <u>09/18/2017</u>

Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment. Not in use - Steel 1" supply gas line stubbed up at front of separator and stubbed up out at wellhead. Not in use - Steel 2" line stub up at front of separator to stub up inside tank berms. Corrective action not completed. Corrective action date remains the same to document days of noncompliance.		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: <u>05/30/2017</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Flow Line	# 1		corrective date
Comment:	Not in use - Steel 2" line stub up at front of separator to stub up inside tank berms.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	Not in use - Steel 1" supply gas line stubbed up at front of separator and stubbed up out at wellhead.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:	Above ground 210 BBL steel tank with earthen berms.				
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	210 BBLS
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds growing inside and on berms.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 10/08/2017

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 208991 Type: WELL API Number: 033-06096 Status: PR Insp. Status: PR

Producing Well

Comment: [PR - Review of electronic well file indicates last reported production was May 2017 with oil/gas reported as 58/5383.](#)

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Well was running at time of inspection.	stjohnw	08/31/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401398685	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4247101
685303723	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4247088