

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2017

Submitted Date:

09/11/2017

Document Number:

679400188

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
CHESSON, BOB 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10548

Name of Operator: HRM RESOURCES II LLC

Address: 410 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Precup, Jim		james.precup@state.co.us	
Pape, Terry	303-893-6621	tpape@hrmres.com	All Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449650	SPILL OR RELEASE	AC	03/16/2017		-	SPILL/RELEASE POINT	AC

General Comment:

Inspected flowline excavation location. Flowline has been repaired and tested. Excavation still open with water present. Hose present that appears to be used to periodically vacuum fluids for disposal. No evidence of recent fluid removal observed. Fluid in excavation has oil sheen. Spill was in March 2017 and staff expectations are for spill resolution (either documented cleaned-up or submittal of a Form 27 for further remediation) within a 90-day time period. Spill remain unresolved after more than 90-days.

HRM is instructed to complete spill clean-up actions or file a Form 27 for further site investigation/remediation by 10/08/17 or staff may pursue possible enforcement actions.

Environmental**Spills/Releases:**Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: Flowline release (Spill/release 401234377). Clean-up actions appear to not have been completed. Documentation of clean-up actions not submitted.Corrective Action: Spill was in March 2017 and staff expectations are for spill resolution (either documented cleaned-up or submittal of a Form 27 for further remediation) within a 90-day time period. Spill remain unresolved after more than 90-days. HRM is instructed to complete spill clean-up actions or file a Form 27 for further site investigation/remediation by 10/08/17 or staff may pursue possible enforcement actions.Date: 10/08/2017Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: 0

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Inspected flowline excavation location. Flowline has been repaired and tested. Excavation still open with water present. Hose present that appears to be used to periodically vacuum fluids for disposal. No evidence of recent fluid removal observed. Fluid in excavation has oil sheen. Spill was in March 2017 and staff expectations are for spill resolution (either documented cleaned-up or submittal of a Form 27 for further remediation) within a 90-day time period. Spill remain unresolved after more than 90-days. See photographs in attachments.	chessonr	09/11/2017
HRM is instructed to complete spill clean-up actions or file a Form 27 for further site investigation/remediation by 10/08/17 or staff may pursue possible enforcement actions.		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401399860	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248314
679400189	Excavated dirt stockpiled at release location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248308
679400190	Excavation location showing fluid	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248309
679400191	Excavation location showing fluid	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248310
679400192	Excavation showing "oil" sheen	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248311
679400194	Hose used to evacuate excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248312
679400195	Excavation showing "oil" sheen	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248313