

COGCC conducted an inspection of the Wells Ranch USX BB 11-06 location (Location ID 310656) on August 24, 2017 (Document 684904162). During that inspection, COGCC made the following observations:

1. Storm Water: Stormwater erosion along lease road. Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Response: Noble has repaired the erosion on the lease road. The vegetation has also been mowed.

Name: Wells Ranch USX BB 11-06

Location ID: 310656

COGCC conducted an inspection of the Wells Ranch USX BB 11-06 location (Location ID 310656) on August 24, 2017 (Document 684904162). During that inspection, COGCC made the following observations:

1. Storm Water: Stormwater erosion along lease road. Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

COGCC – 8/24/17



Photo 2: Stormwater erosion on lease road, looking E

Noble Energy – 9/13/17



Photo NBL1. Noble has repaired erosion on the lease road and mowed vegetation.