

**Inspection Photos**  
**Location Name: Miller 33-29**  
**API #: 05-123-19479**  
**Location ID: 330698**



**Wellheads looking east, weeds need to be controlled**



**Stained soil under master valve**

**Inspection Photos**  
**Location Name: Miller 33-29**  
**API #: 05-123-19479**  
**Location ID: 330698**



**Battery looking west**



**Unused/disconnected gas meter run north of separator**