

Inspection Photos
Location Name: Bayless API 103-07822
Pit Closure
9/28/2017



Pit looking Northwest



Possible flowline riser near pit