

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2017

Submitted Date:

09/26/2017

Document Number:

684904469**FIELD INSPECTION FORM**Loc ID 331062 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	<a href="#">All Inspections</a>
Anderson, Austin	918-845-4700	aanderson@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258177	WELL	PR	11/01/2000	GW	123-20097	HOFFMAN 34-10	PR

**General Comment:**

## Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	hydrogen sulfide scavenger		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Oily weed debris at NW corner of southern pit, and between the pits		
Corrective Action:	Comply with Rule 603.f .	Date:	10/06/2017
Type	WEEDS		
Comment:	Weeds in pit		
Corrective Action:	Comply with Rule 603.f .	Date:	10/06/2017

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Stained soil at pump jack, floating fluids		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS 48-hrs To perform cleanup. 5 days to contact Area EPS	Date:	09/28/2017
Type: Vertical Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	engine; stained soil at engine and exhaust		
Corrective Action:	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	10/26/2017
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	pumps- 1 hydrogen sulfide scavenger		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		40.621320,-104.075340
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	110bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shared with produced water				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		40.621320,-104.075340
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.621520,-104.075610
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	258177	Type:	WELL	API Number:	123-20097	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	
BradenHead									
Comment:		Bradenhead not plumbed to surface.							
Corrective Action:								Date:	

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced Water

Lined:

Pit ID: 273443Lat: 40.621436Long: -104.074689Reference Point: Other: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Action: Date: c**Fencing:**

Fencing Type:

Fencing Condition:

Comment: Corrective Action: Date: **Netting:**

Netting Type:

Netting Condition:

Comment: Corrective Action: Date: 

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YESComment: Adjacent to produced water pitCorrective Action: Date: Type: Produced Water

Lined:

Pit ID: 273442Lat: 40.621210Long: -104.075049Reference Point: Other: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Action: Date: c**Fencing:**

Fencing Type:

Fencing Condition:

Comment: Corrective Action: Date: **Netting:**

Netting Type:

Netting Condition:

Comment:		Date:
Corrective Action		
Anchor Trench Present: Oil Accumulation: <u>NO</u> 2+ feet Freeboard: <u>YES</u>		
Comment:	Produced water pit with open top skim. Gaps in mesh on skim pit.	Date: <u>09/27/2017</u>
Corrective Action	Net or fence pit to prevent access per rule 902.d.	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401414205	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4260366">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4260366</a>
684904473	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4260361">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4260361</a>