

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2017

Submitted Date:

10/05/2017

Document Number:

689300253

FIELD INSPECTION FORM

Loc ID 336706 Inspector Name: O'Donnell, Shaun On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202

Findings:

- 16 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251399	WELL	PR	06/01/2017	GW	123-19202	SCHANK J 35-06	SI
292187	WELL	PR	02/29/2008	GW	123-26252	SCHANK J 35-20	PR
293009	WELL	PR	06/01/2017	GW	123-26443	SCHANK J 35-21	PR

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		Date:
Corrective Action:			

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	2-unused gas meter runs on location. They need to be removed. See attached photos		
Corrective Action:	Comply with Rule 603.f .	Date:	01/05/2018
Type	WEEDS		
Comment:	Actively growing weeds on location, need to be controlled. See attached photos		
Corrective Action:	Comply with Rule 603.f .	Date:	10/15/2017

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Steel panel		
Corrective Action:		Date:	

Equipment:			
Type: Ancillary equipment	# 2		corrective date
Comment:	2-ECD knockouts. 1 at tanks, 1 at ECD		
Corrective Action:		Date:	

Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:	1 in service, 2 disconnected		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	<50 BBLs	PBV CONCRETE		
Comment:	48 BBLs				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berm with crude oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.358760,-104.751160
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 251399 Type: WELL API Number: 123-19202 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is configured to produce, not producing at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead valve is exposed at surface

Corrective Action: _____ Date: _____

Facility ID: 292187 Type: WELL API Number: 123-26252 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead valve is exposed at surface

Corrective Action: _____ Date: _____

Facility ID: 293009 Type: WELL API Number: 123-26443 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is configured to produce, not producing at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead valve is exposed at surface

Corrective Action: _____ Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
Gravel	Fail					

Comment: [Location is washing out northeast of tank battery and running along east side of tank battery, discharging at southeast edge of location. Sediment is carrying off into field. Location is also starting to wash out between tank battery and separators. See attached photos](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 11/05/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300254	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4268398