

## Inspection Photos



**Photo 1.** Facing northeast toward the location. The location has not been recontoured and reclaimed.

## Inspection Photos



**Photo 2.** There are signs of erosion occurring off the southwestern portion of the pad.



## Inspection Photos



**Photo 3.** East side of the location facing northwest toward the location. The brown vegetation is undesirable weed growth ( Russian thistle).

## Inspection Photos



**Photo 4.** Facing northeast toward the cut slope of the location. The desirable vegetation has not re-established



## Inspection Photos



**Photo 5.** There is undesirable weed growth (*Salsola* sp.) throughout the location.



## Inspection Photos



**Photo 6.** Facing north off the location toward the undisturbed vegetation.