

Photo#1:
Overview of Location from NE corner to SW.



October 4, 2017

Photo#2:
View along West side of Location.



October 4, 2017

Photo#3:

Mixture of Grubbing material & Top Soil which appears to be used as unconsolidated berm/ BMP on North side of Location.



October 4, 2017

Photo#4:

Adjacent to Site is Irrigation Ditch running North to South, Curling around East side of Location. Circle shows Flagging for LOD.



October 4, 2017

Photo#5:

Point on Access Road at turn into Location where SW is draining off Road into Irrigation Ditch (indicated with arrow). BMPs need to be installed/ repaired along Access Road



October 4, 2017

Photo#6:

Top Soil Pile piled at SW edge of what will be (per Operator) LOD when Location is Amended for future development.



October 4, 2017