

Inspection Photos



Photo 1. 2015 aerial image of the access road and location.

Inspection Photos



Photo 2. Beginning of the access road facing south.

Inspection Photos



Photo 3. Facing southeast along the access road. There is predominately undesirable weeds (Kochia) growing along the road. There is no gravel present along the road.

Inspection Photos



Photo 4. Facing southeast along the access road. The area along the side of the road contains undesirable weeds and is not adequately stabilized with desirable vegetation.

Inspection Photos



Photo 5. There are signs of stormwater erosion occurring along the road.

Inspection Photos



Photo 6. Facing southwest along the access road. There is stormwater held back by the road on the eastern side. There is a potential for stormwater to flow across the road causing erosion however there was minimal signs of this occurrence.

Inspection Photos



Photo 7. Facing southwest along the access road where it gradually ascends. There is erosion occurring from this point at the bottom of the slope all the way to the top near the location. Approximately 1500 ft.

Inspection Photos



Photo 8. Facing south where access road continues to ascend to the location. There is erosion occurring down the slope of the road.

Inspection Photos



Photo 9. There is erosion occurring down the slope of the road. The arrow points to a 3.5 ft. shovel in the erosion channel which indicates depth.

Inspection Photos



Photo 10. Facing west toward the location at the top of the hill.

Inspection Photos



Photo 11. Facing northwest at the location.

Inspection Photos



Photo 12. Facing southwest along the fill slope of the location.

Inspection Photos



Photo 13. Northwest side of the location facing southeast.

Inspection Photos



Photo 14. Northwest side of the location facing south along the fill slope.

Inspection Photos



Photo 15. West side of the location facing east.

Inspection Photos



Photo 16. Facing northwest at the location.