

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2017

Submitted Date:

10/04/2017

Document Number:

689300251**FIELD INSPECTION FORM**
 Loc ID 326934 Inspector Name: O'Donnell, Shaun On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Pennington, David		dpennington@syrginfo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246086	WELL	PR	02/05/2004	OW	123-13883	STROH 35-1	SI

General Comment:

Location					
Lease Road:					
Type	Access				
comment:	Wellhead is in active crops				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	Wellhead sign is reading the Stroh 35-2, well is the Stroh 35-1				
Corrective Action:	Install sign to comply with Rule 210.b.				Date: 12/04/2017
Emergency Contact Number:					
Comment:	Adequate				
Corrective Action:					Date: _____
Good Housekeeping:					
Type	WEEDS				
Comment:	Actively growing weeds at wellhead need to be controlled. See attached photos				
Corrective Action:	Comply with Rule 603.f .				Date: 10/14/2017
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	WELLHEAD				
Comment:	Steel pipe				
Corrective Action:					Date:
Equipment:					
				corrective date	
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	See API 05-123-13886 for equipment inventory				
Corrective Action:					Date:
Paint					
Condition					

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	246086	Type:	WELL	API Number:	123-13883	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Well is configured to produce, not producing at time of inspection"/>									
Corrective Action: <input type="text"/> Date: _____									
BradenHead									
Comment: <input type="text" value="Bradenhead valve is exposed at surface"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401420531	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4267133
689300252	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4267130