

Photo#1:
Overview of Location to North East.



September 26, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Nat Res JSR 4-1 API#081-07070

Photo#2:

Heavy infestation of Scotch Thistle on Fill Slope.



September 26, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Nat Res JSR 4-1 API#081-07070

Photo#3:

View of Site from bottom of Fill Slope to Cut Slope @ South East.



September 26, 2017

Photo#4:

Scotch Thistle established within the 25 ft. Safety Zone of Well Head.



September 26, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Nat Res JSR 4-1 API#081-07070

Photo#5:
Unmarked Guy Anchor surrounded by Russian Thistle.



September 26, 2017

Photo#6:
Metal & Thistle Debris in Pad area.



September 26, 2017

Photo#7:

Looking out from Access Road Entry to South East.



September 26, 2017




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Nat Res JSR 4-1 API#081-07070

Photo#8:

Looking North West from Access Road Entry, along Road which is defined by Scotch Thistle growth. Arrow indicates point at which road turns to West towards Location. Road is approximately $\frac{3}{4}$ of a mile in length.



September 26, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Nat Res JSR 4-1 API#081-07070

Photo#9:

Close up of Thistle on Access Road..



September 26, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Nat Res JSR 4-1 API#081-07070