

Final Reclamation Inspection

October 5, 2017

Operator: CHESAPEAKE OPERATING LLC- 16660

API: 05-123-34095

Weld County, CO

SWSW Section 24 T9N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HEDIGER 24-9-67 #1H
API: 05-123-34095



Photo 1. Photo taken from the entrance of the well location, facing North. Appears the gate and fence material around the entire location remains.



Photo 2. Photo taken from the entrance of the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: HEDIGER 24-9-67 #1H
API: 05-123-34095



Photo 3. Photo taken from the approximate center of the well location, facing West. Unable to find evidence of oil and gas activities and/or disturbances. Well location appears reflective of reference areas.



Photo 4. Photo taken from the approximate center of the well location, facing North. See comments under Photo 3.

Inspection Photos
Location Name: HEDIGER 24-9-67 #1H
API: 05-123-34095



Photo 5. Photo taken from the approximate center of the well location, facing East. See comments under Photo 3.



Photo 6. Photo taken from the approximate center of the well location, facing South. See comments under Photo 3.

Inspection Photos

Location Name: HEDIGER 24-9-67 #1H

API: 05-123-34095



Photo 7. Photo taken from the entrance of the well location, facing East. See comments under Photo 1. .



Photo 8. Photo taken from the entrance of the location, facing West. Culvert remains at the entrance of the location.