

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/04/2017

Submitted Date:

10/07/2017

Document Number:

680102275**FIELD INSPECTION FORM**

Loc ID 413754	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 9 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10598</u> Name of Operator: <u>SANDRIDGE EXPLORATION & PRODUCTION LLC</u> Address: <u>123 ROBERT S KERR AVE</u> City: <u>OKLAHOMA CITY</u> State: <u>OK</u> Zip: <u>73102</u>				

Contact Information:

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@san dridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412904	WELL	PR	04/15/2014	OW	057-06499	HEBRON 02-07H	CI
412906	WELL	DG	02/27/2017	LO	057-06497	Marr 0780 1-6H31	CI
446420	WELL	XX	06/29/2016		057-06556	Marr 0780 7-6H31	CI
446421	WELL	DG	08/14/2016	OW	057-06557	Marr 0780 5-6H31	CI
446422	WELL	DG	08/12/2016	OW	057-06558	Marr 0780 6-6H31	CI
446423	WELL	XX	06/29/2016		057-06559	Marr 0780 8-6H31	CI
447274	WELL	DG	08/18/2016	OW	057-06575	Marr 0780 2-6H31	CI

General Comment:

This is a Post Construction and Stormwater Inspection. Form 42 : NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 9/18/17. This appears to be an Amendment to an Existing Location, housing PR Well API#057-06499. Conditions at time of Inspection were Sunny skies at 50 degrees F. Elevation at Site is 8,130 ft. Construction of Pad appears to be complete; SW & Vegetation issues are discussed in Reclamation Section.

Location Construction

Location ID: 413754 CDP: _____

Comment: One PR Well is on Location. It appears that any Amendment to Existing Location has been completed; Conductors have been Set. Location is Well compacted & Graveled. Cellars of Conductors have efficient grate covers installed, insuring Wildlife & Workplace Safety. Stormwater & vegetation is addressed in Reclamation/ Storm Water Section.

Corrective Action: _____

Date: _____**Form 2A COAs:****Comment:** _____

Corrective Action: _____

Date: _____**Wildlife BMPs:****Comment:** This Location is in a Sensitive Wildlife Habitat; Greater Sage Grouse

Corrective Action: _____

Date: _____

Comment: Inspection was conducted after a significant precipitation event. Area had received heavy rainfall & Snow two days prior to Insp Date; Snow Melt was in process at time of Insp. Stormwater & vegetation is addressed in Reclamation Stormwater Section.

Corrective Action: _____**Date:** _____**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities				
Facility ID: <u>412904</u>	Type: <u>WELL</u>	API Number: <u>057-06499</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>412906</u>	Type: <u>WELL</u>	API Number: <u>057-06497</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446420</u>	Type: <u>WELL</u>	API Number: <u>057-06556</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446421</u>	Type: <u>WELL</u>	API Number: <u>057-06557</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446422</u>	Type: <u>WELL</u>	API Number: <u>057-06558</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446423</u>	Type: <u>WELL</u>	API Number: <u>057-06559</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447274</u>	Type: <u>WELL</u>	API Number: <u>057-06575</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____ F _____

Comment It appears Conductors have been Set recently on Location & that Drilling may be imminent. Infestation of Canada Thistle (B List Noxious Weed) was noted on outside of Berm on West side of Location.

Corrective Action Control Noxious Weeds. Controls should be applied ASAP as short time window is left for effective application.

Date **10/18/2017**

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds	In Process					Wier gate to be installed @ NW Corner
Other	Fail					No BMPs on East Perimeter
Waddles	Fail					BMPs have been compromised
Gravel	Pass					
Slope Roughening	Pass					
Ditches	Pass					

Comment: [Wattles, on West side of Site have been dislodged from installation by Livestock. There are no apparent Sediment Controls installed on East side perimeter of Location. North end has Slope Roughening; South end has Ditch on perimeter. Operator indicated Installation/Repair of BMPs would be performed ASAP.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f. Refer to Photos attached.](#)

Date: 10/23/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401424846	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270692
680102278	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270656