

Inspection Photos



Photo 1. 2015 aerial image shows access road and location disturbance.

Inspection Photos



Photo 2. Facing northeast toward the access road which has not been reclaimed.

Inspection Photos



Photo 3. Facing northeast toward the location. The location has a perimeter fence that is not maintained.

Inspection Photos



Photo 4. Center of the location facing north. There are undesirable weeds throughout the location (Russian thistle).

Inspection Photos



Photo 5. Center of the location facing west. There are undesirable weeds throughout the location (Russian thistle).

Inspection Photos



Photo 6. Center of the location facing south.

Inspection Photos



Photo 7. Center of the location facing east.

Inspection Photos



Photo 8. The 3.5 ft. shovel indicates height of weed debris throughout the location.

Inspection Photos



Photo 9. East side of the location facing west. A 100 ft. tape measure shows the extent of this portion of the location without any desirable vegetation establishment.

Inspection Photos



Photo 10. The fence around the location is not maintained. The barbed wire is only about 1 ft. off the ground and livestock can access the site.

Inspection Photos



Photo 7. Facing north off the location toward the undisturbed vegetation.