

Inspection Photos



Photo 1. 2015 aerial image shows the location disturbance.

Inspection Photos



Photo 2. Facing east along the access road toward the location.

Inspection Photos



Photo 3. Facing southeast toward the location. The location has a perimeter fence that is not maintained.

Inspection Photos



Photo 4. Center of the location facing north. There are undesirable weeds throughout the location (Russian thistle, Kochia sp.).

Inspection Photos



Photo 5. Center of the location facing west. There are undesirable weeds throughout the location (Russian thistle, Kochia sp.).

Inspection Photos



Photo 6. Center of the location facing south.

Inspection Photos



Photo 7. Center of the location facing east.

Inspection Photos



Photo 8. The 3.5 ft. shovel indicates height of weed debris throughout the location.

Inspection Photos



Photo 9. View of ground cover at the location. There is predominately undesirable vegetation (Russian thistle, Kochia sp.) and bare soil.

Inspection Photos



Photo 10. Facing northwest at the location. A 100 ft. tape measure shows the extent of this portion of the location without any desirable vegetation establishment.

Inspection Photos



Photo 11. The fence around the location is not maintained. The barbed wire is only about 1 ft. off the ground and livestock can access the site.

Inspection Photos



Photo 12. Facing north off the location toward the undisturbed vegetation.