

Inspection Photos



Photo 1. Facing north along the former access road which still present.

Inspection Photos



Photo 2. Facing north along the former access road which has not been reclaimed.

Inspection Photos



Photo 3. There are two pipe risers that remain at the location.

Inspection Photos



Photo 4. There is an OXY sign at one of the risers at the location.

Inspection Photos



Photo 5. Facing north toward the location. The vegetation has not re-established at the location.

Inspection Photos



Photo 6. Facing south at the location. The vegetation has not adequately re-established and the soils appear to be compacted.

Inspection Photos



Photo 7. Facing east toward the surrounding undisturbed pasture.