

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2017

Submitted Date:

10/10/2017

Document Number:

690900002**FIELD INSPECTION FORM**Loc ID 440549 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hogelin, Thomas G.		THogelin@bry.com	
Armstrong, Jon		jarmstrong@bry.com	
Hughes, Jim		jimo.hughes@state.co.us	
Colby, Lou		lou.colby@state.co.us	
Lujan, Carlos		carlos.lujan@state.co.us	
Johnson, Derek S		DJohnson@bry.com	
Ramos, Martha		martha.ramos@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436375	CENTRALIZED EP WASTE MGMT FAC	AC	02/09/2015		-	House Log Gulch Tank Farm	AL

General Comment:

On September 20, 2017 COGCC Staff (Alex Fischer, Margaret Ash, Carlos Lujan, Lou Colby, and Jim Hughes) conducted field inspections of Berry Petroleum's House Log Gulch Tan Farm Centralized E&P Facility ID:436375. Berry Petroleum representatives Tom Hogelin and Derek Johnson were present during the site visit. The purpose of the inspection is that Linn Operating LLC - Operator #10516, have requested a bond release for Surety ID#2017-0034 for the House Log Gulch Tank Farm E&P Waste Facility #436375. The operator has stated that this facility was never built.

The existing Location has been and is currently used as a storage and laydown yard. Equipment noted on site include:
pipes,
racks,
dumpster, and
equipment.

It does not appear that the House Log Gulch Tank Farm had been constructed.

Inspected Facilities									
Facility ID:	436375	Type:	CENTRALIZE	API Number:	-	Status:	AC	Insp. Status:	AL

--

Environmental**Spill/Remediation:**Comment: It appears that the House Log Gulch Centralized E&P Waste Management Facility was never constructed.

Corrective Action: Per Rule 908.g.(2) submit an eForm 27 providing a statement that the House Log Gulch Centralized E&P Waste Management Facility was never constructed. It is suggested that this Inspection Document Number 690900002 be referenced on the eForm 27.

Per Rule 1004.c.(4) submit an eForm 4 providing a statement that the House Log Gulch Centralized E&P Waste Management Facility was never constructed. It is suggested that this Inspection Document Number 690900002 be referenced on the eForm 4.

Date: 12/10/2017

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On September 20, 2017 COGCC Staff (Alex Fischer, Margaret Ash, Carlos Lujan, Lou Colby, and Jim Hughes) conducted field inspections of Berry Petroleum's House Log Gulch Tan Farm Centralized E&P Facility ID:436375. Berry Petroleum representatives Tom Hogelin and Derek Johnson were present during the site visit. The purpose of the inspection is that Linn Operating LLC - Operator #10516, have requested a bond release for Surety ID#2017-0034 for the House Log Gulch Tank Farm E&P Waste Facility #436375. The operator has stated that this facility was never built.</p> <p>The existing Location has been and is currently used as a storage and laydown yard. Equipment noted on site include: pipes, racks, dumpster, and equipment.</p> <p>It appears that the House Log Gulch Centralized E&P Waste Management Facility was never constructed.</p> <p>Per Rule 908.g.(2) submit an eForm 27 providing a statement that the House Log Gulch Centralized E&P Waste Management Facility was never constructed. It is suggested that this Inspection Document Number 690900002 be referenced on the eForm 27.</p> <p>Per Rule 1004.c.(4) submit an eForm 4 providing a statement that the House Log Gulch Centralized E&P Waste Management Facility was never constructed. It is suggested that this Inspection Document Number 690900002 be referenced on the eForm 4.</p>	fischera	10/10/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401424834	INSP Location ID 440549 CE and P Facility ID 436375 20170920 Photo	INSP Location ID 440549 CE and P Facility ID 436375 20170920 Photo.pdf
401424863	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270704
690900003	INSP Location ID 440549 CE and P Facility ID 436375 20170920 Photo	INSP Location ID 440549 CE and P Facility ID 436375 20170920 Photo.pdf