

Inspection Photos  
Location Name: Dakota Fee 1  
API: 05-06141  
Inspection Number: 685200403



8.17.17 photo showing tall weeds within 25' of equipment



10.4.17 photo showing weeds not fully removed, now dead and combustibile

Inspection Photos  
Location Name: Dakota Fee 1  
API: 05-06141  
Inspection Number: 685200403



8.17.17 photo of tank berms



10.4.17 photo showing tall vegetation removed from inside berms (note: roots still present)



Inspection Photos  
Location Name: Dakota Fee 1  
API: 05-06141  
Inspection Number: 685200403



8.17.17 photo of unmarked container



10.4.17 corrective action performed

Inspection Photos  
Location Name: Dakota Fee 1  
API: 05-067-06141  
Inspection Number: 685200403



**Oily rag on ground**



Inspection Photos  
Location Name: Dakota Fee 1  
API: 05-067-06141  
Inspection Number: 685200403



**Heavily rutted shared access road**

**Inspection Photos**

**Location Name: Dakota Fee 1**

**API: 05-067-06141**

**Inspection Number: 685200403**



**Rutting and sediment migration on operator only portion of access (needs BMP such as but not limited to culvert)**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources