

## Inspection Photos



**Photo 1.** 2015 aerial image shows access road and location disturbance still exists.

## Inspection Photos



**Photo 2.** Facing south along the access road. The desirable vegetation has not re-established.



## Inspection Photos



**Photo 3.** Facing south toward the location. The desirable vegetation has not re-established.



## Inspection Photos



**Photo 4.** Facing north at the location. A 100ft. tape measure extent of inadequate vegetation establishment at the location.



## Inspection Photos



**Photo 5.** South side of the location facing north. The dark vegetation is undesirable weeds (Russian thistle, Kochia sp.) which have become debris.



## Inspection Photos



**Photo 6.** View of groundcover at the location. There is predominately undesirable weeds (*Kochia* sp., *R. thistle*) throughout the location.



## Inspection Photos



**Photo 7.** Facing east off the location toward the undisturbed vegetation.