

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/19/2017

Submitted Date:

10/19/2017

Document Number:

679903260**FIELD INSPECTION FORM**

Loc ID 320954 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 88380Name of Operator: TINDALL OPERATING COMPANYAddress: 12741 E CALEY STE 142City: CENTENNIAL State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Tucker, Lee	303-850-7272 off/10097	rleetuck@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205432	WELL	PR	04/01/2016	GW	009-05117	COOK 1-5	PR

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track through CRP		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Rods and tubing laying on the ground next to unit. Note from previous inspection in 2015 shows it has been stored on location for over 2 years.		
Corrective Action:	Remove unused equipment. Comply with Rule 603.f.		Date: 01/19/2018
Type	WEEDS		
Comment:	Maintain weeds on location		
Corrective Action:	Comply with Rule 603.f .		Date: 10/29/2017
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Pipe fence around meter shed and pig station		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Flow Line	# 1		
Comment:	Unmarked flowline		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag 30 days to remove riser.		Date: 11/19/2017
Type: Pump Jack	# 1		
Comment:	Lufkin unit		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:	Next to meter shed		

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	In meter shed		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Day drum and gas scrubber		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator next to wellhead		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		37.194770,-102.279110
Comment:	Fiberglass open top water tank w/Adequate wildlife screening				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	205432	Type:	WELL	API Number:	009-05117	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is SI at time of inspection. No production since May 2016.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
The wellhead has corrosion and a leak was detected. The corrosion is extensive from the ground to the tubing valve. Repair the gas leak. Also, there was an audible, continuous water gargle from the painted piece of pipe that was disconnected from the water leg at the wellhead.	welshb	10/19/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679903261	There was a leak detected on the wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4279579">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4279579</a>
679903262	Remove all unused equipment on location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4279580">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4279580</a>