

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2017

Submitted Date:

10/20/2017

Document Number:

689400514**FIELD INSPECTION FORM**
 Loc ID 322379 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Allred, Josh	(970) 629-5914	jallred@foundationenergy.com	Field Supervisor
Fischer, Alex		alex.fischer@state.co.us	
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Contact, General		regulatory@foundationenergy.com	Regulatory

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111739	PIT		09/23/1999		-	FEDERAL 15-15	
210387	WELL	PR	05/29/1978	GW	045-06143	FEDERAL 15-15	PR

**General Comment:**

**Location****Lease Road:**

Type	Access		
comment:	See stormwater section of inspection.		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	111739	Type:	PIT	API Number:	-	Status:		Insp. Status:	
Facility ID:	210387	Type:	WELL	API Number:	045-06143	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:							Date:		

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Main road from Baxter Pass Road to location has multiple areas of erosion across roadway and sediment migration down gradient of road surface. This location is a federal surface hence the inspection is being forwarded to a BLM representative so they may respond to the operator on what actions should be implemented. The road would not meet the COGCC stormwater rules for erosion and sediment migration.

Corrective Action:  Date:

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Evaporation Lined: NO Pit ID: 111739 Lat: 39.446784 Long: -108.972572

Reference Point:  Other:  Length:  Width:

**Lining:**

Liner Type:  Liner Condition:

Comment:

Corrective Action:  Date: c

**Fencing:**

Fencing Type: Livestock Fencing Condition: Inadequate

Comment: Fence is falling into pit and not maintained.

Corrective Action: Net or fence pit to prevent access per rule 902.d. Date: 10/27/2017

**Netting:**

Netting Type: Mesh Netting Condition: Sagging into pit contents

Comment: Mess is sagging and falling into pit and not maintained.

Corrective Action: Net or fence pit to prevent access per rule 902.d. Date: 10/27/2017

Anchor Trench Present:  Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action:  Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689400515	Federal 15-15	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4280128">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4280128</a>