

Inspection Photos
Location Name: Frye Farms Pad 44-32
API: 05-123-34946



Photo 1: Sound study location, looking SE



Photo 2: Stained soil at wellhead

Inspection Photos
Location Name: Frye Farms Pad 44-32
API: 05-123-34946



Photo 3: Stained soil at wellhead



Photo 4: Stained soil at wellhead

Inspection Photos
Location Name: Frye Farms Pad 44-32
API: 05-123-34946



Photo 5: Stained soil at VRU



Photo 6: Stormwater erosion at SW corner of location, looking W

Inspection Photos
Location Name: Frye Farms Pad 44-32
API: 05-123-34946



Photo 7: Stormwater erosion on W side of battery, looking W



Photo 8: Stormwater erosion on S side of location, looking W