

Inspection Photos



Photo 1. Facing northwest toward the location.

Inspection Photos



Photo 2. There is storage of pipe at the northeast corner of the location.

Inspection Photos



Photo 3. Northeast corner of the location facing west.

Inspection Photos



Photo 4. Facing northeast at the location. Unused areas of the location have not been reclaimed.

Inspection Photos



Photo 5. There are degraded hay bales that remain around the location that have not been removed.

Inspection Photos



Photo 6. West side of the location facing south.

Inspection Photos



Photo 7. There are List B noxious weeds that have not been removed along the west side of the location. There were also numerous rosettes growing in this area. The red arrow points to the Scotch thistle which has dispersed seed.

Inspection Photos



Photo 8. Facing south where the unpermitted disturbance occurred. The area where the access road was built does not have vegetation establishment. The soils appear to be compacted. The red arrow points toward an area of stormwater erosion rill.

Inspection Photos



Photo 9. Facing east where the unpermitted disturbance occurred. The vegetation appears to be re-establishing and appears to be predominately Smooth brome.

Inspection Photos



Photo 10. View of vegetation establishment which appears to be predominately Smooth brome.

Inspection Photos



Photo 11. Facing north where the unpermitted disturbance occurred. The area where the access road was built (western side) does not have as much vegetation establishment. The soils appear to be compacted.

Inspection Photos



Photo 12. There are areas where the soils appear to be compacted. The shovel is unable to penetrate the soil surface.

Inspection Photos



Photo 13. Facing west off the location toward the undisturbed vegetation.