

- Tyner – Lunt (EPA) 1
- 05-067-06140



Photo 1: Wellhead sign.

- Tyner – Lunt (EPA) 1
- 05-067-06140



Photo 2: Unmarked anchor.

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 3: Unmarked anchor.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 4: Well pad overview.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 5: Erosion channel at E side of tank battery.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 6: Erosion channels along S perimeter.**



- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 7: Erosion channel on W side of tank battery.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 8: Liner detached from wall.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 9: Tears in bottom of liner.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 10: Injection facility overview.**