

Inspection Photos
Location Name: E. Johnson 2-21
API #: 05-123-21260
Location ID: 331761



Wellhead looking north



Battery looking west

Inspection Photos

Location Name: E. Johnson 2-21

API #: 05-123-21260

Location ID: 331761



Access road to battery looking north 9-12-2017



Access road to battery looking north 10-23-2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: E. Johnson 2-21

API #: 05-123-21260

Location ID: 331761



Access road to wellhead from battery looking southeast. Road is washing out on both sides 9-12-2017



Access road from wellhead to battery looking northwest. Still washing out 10-23-2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: E. Johnson 2-21

API #: 05-123-21260

Location ID: 331761



Location washing out south side of separator 9-12-2017



Location washing out south side of separator 10-23-2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: E. Johnson 2-21

API #: 05-123-21260

Location ID: 331761



Location washing out north side of location, discharging northwest of tank battery with sediment carrying off into field 9-12-2017



Location washing out north side of location, discharging northwest of tank battery with sediment carrying off into field 10-23-2017



Inspection Photos

Location Name: E. Johnson 2-21

API #: 05-123-21260

Location ID: 331761



Entrance of location looking south, washing out 10-23-2017



Northeast edge of tank battery is washing out 10-23-2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: E. Johnson 2-21

API #: 05-123-21260

Location ID: 331761



Actively growing weeds on access road from tank battery to wellhead. Needs to be controlled



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources