

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/19/2017

Submitted Date:

10/23/2017

Document Number:

685303902

**FIELD INSPECTION FORM**

Loc ID 325354 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74500  
Name of Operator: REYNOLDS\* NOEL  
Address: BOX 356  
City: FLORA VISTA State: NM Zip: 87415

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214628	WELL	SI	03/01/1993	GW	067-06232	ESTER 1	SI

**General Comment:**

[See link at end of report for path to downloadable pictures.](#)

This is an orphan well inspection with emphasis on critical maintenance and abandonment. No previous corrective actions performed, corrective actions are still required.

With no current operator this well inspection included portions of May 2017 Flowline NTO to mark and inventory flowline risers. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	No corrective action completed. Task will need to be generated to repair road in order to gain access for any work at well site.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?


<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical service equipment.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Power pole and meter.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Located (2) deadmen.		
Corrective Action:	Locate and mark all deadmen.	Date:	11/23/2017
Type: Flow Line	# 1		
Comment:	In use - 3" line from wellhead. (B) point is unknown.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	



**Inspected Facilities**

Facility ID: 214628 Type: WELL API Number: 067-06232 Status: SI Insp. Status: SI

**COGCC Comments**

Comment	User	Date
Tasks will likely include access road repair, P&A of well, Electrical service equipment removal, flowline removal/abandonment, and site clean up. Pit on location may require impacted material removal, possible sampling and analysis? TBD by Enviro. Additional finding of (2) rig anchors will require locate and removal of all anchors. Possible removal of power pole and meter that were run to location. Initial reclamation work on access road and location will be needed when all other work is completed.	stjohnw	10/23/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303909	Inspection pictures.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281956">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281956</a>